

Data Completeness Table (FY2009)		
States	Majors DMR Entry Rate	Minors DMR Entry Rate
Alabama	98.08%	45.38%
Alaska	76.32%	37.14%
Arizona	86.49%	14.66%
Arkansas	99.09%	95.74%
California	90.73%	2.05%
Colorado	99.10%	38.46%
Connecticut	100.00%	93.75%
Delaware	95.24%	90.63%
District Of Columbia	100.00%	100.00%
Florida	83.82%	84.87%
Georgia	97.81%	49.62%
Hawaii	100.00%	12.61%
Idaho	91.67%	88.12%
Illinois	97.61%	85.13%
Indiana	100.00%	96.28%
Iowa	67.44%	34.99%
Kansas	92.73%	1.94%
Kentucky	86.15%	0.28%
Louisiana	97.64%	10.92%
Maine	88.24%	54.17%
Maryland	100.00%	76.46%
Massachusetts	98.17%	77.94%
Michigan	88.27%	60.23%
Minnesota	88.30%	2.66%
Mississippi	90.11%	22.04%
Missouri	89.60%	58.53%
Montana	97.30%	90.68%
Nebraska	100.00%	73.42%
Nevada	76.92%	0.00%
New Hampshire	100.00%	67.50%
New Jersey	98.64%	16.23%
New Mexico	97.30%	85.71%
New York	98.75%	88.70%
North Carolina	96.31%	90.95%
North Dakota	73.08%	1.03%
Ohio	96.23%	92.89%
Oklahoma	98.04%	96.10%
Oregon	97.06%	1.57%
Pennsylvania	100.00%	1.58%
Puerto Rico	100.00%	96.25%
Rhode Island	100.00%	76.12%
South Carolina	89.70%	75.34%
South Dakota	93.10%	74.55%
Tennessee	98.59%	21.60%
Texas	93.24%	81.77%
Utah	100.00%	66.39%
Vermont	100.00%	2.01%
Virgin Islands	80.00%	49.25%
Virginia	86.62%	0.11%
Washington	16.22%	11.59%
West Virginia	96.00%	22.34%
Wisconsin	99.22%	1.48%
Wyoming	95.45%	0.45%
National Average	93.32%	40.90%

* EPA remains the permitting authority for the NPDES program
Permit limits and Discharge Monitoring Reports are necessary in order for EPA, states, and the public to view the compliance status for facilities. States with high percentages in the table have more information in EPA's system. NOTE: Although Oregon shows 100% for majors, the compliance data for the state is not available at this time.